





| Roulunds  |          | Abmessung / Size  | ZZ  | Barcode   |
|---|----------|---|---|---|
|  |          |  |  |  |
| RR1040  | 159HG290 | HTDA 1272 8000 M 29   | 159   | 4010858087869   |
| RR1041  | NEU/NEW  | CPPN 1032 8000 M 22 ZZP   | 129   | 4010858088002   |
| RR1042  | NEU/NEW  | CPPN 1000 8000 M 22 ZZP   | 125   | 4010858088019   |
| RR1043  | 265HG320 | HTDA 2120 8000 M 32   | 265   | 4010858088026   |
| RR1044  | NEU/NEW  | HTDA 1067 9,525M 29   | 112   | 4010858088033   |
| RR1045  | NEU/NEW  | HTDA 1457 9,525M 25   | 153   | 4010858088040   |
| RR1046  | 065HG127 | HTDA 520 8000 M 12,7  | 65  | 4010858088057   |
| RR1047  | 150HP290 | HTDA 1429 9,525M 29   | 150   | 4010858088064   |
| RR1048  | 099HG190 | HTDA 792 8M 19 EV   | 99  | 4010858088071   |
| RR1049  | NEU/NEW  | STDN 1520 8000 M 24 ZZP   | 190   | 4010858088088   |
| RR1050  | NEU/NEW  | CPI 1599 8035 M 24 ZZP  | 199   | 4010858088095   |
| RR1454  | 149HP240 | HTDA 1419 9,525M 24   | 149   | 4010858036768   |
| RR1051  | NEU/NEW  | HTDA 1240 8M 24   | 155   | 4010858088101   |
| RR1052  | NEU/NEW  | HTDA 1286 9,525M 25 ZZP   | 135   | 4010858088118   |
| RR1053  | NEU/NEW  | CPPN 1362 9,525M 25   | 143   | 4010858088125   |
| RR1054  | NEU/NEW  | HTDA 1172 9,525M 28   | 123   | 4010858088132   |
| RR1055  | NEU/NEW  | HTDA 1457 9,525M 30   | 153   | 4010858088149   |
| RR1056  | NEU/NEW  | HTDA 791 9,525M 30  | 83  | 4010858088156   |
| RR1057  | NEU/NEW  | HTDA 791 9,525M 24  | 83  | 4010858088163   |
| RR1058  | NEU/NEW  | CPPN 1305 9,525M 25   | 137   | 4010858088170   |
| RR1059  | NEU/NEW  | CHD 1105 9,525M 25,4  | 116   | 4010858088187   |
| RR1060  | 117HP300 | HTDA 1114 9,525M 30   | 117   | 4010858088194   |
| RR1061  | NEU/NEW  | STD 1184 8M 23  | 148   | 4010858088200   |
| RR1455  | NEU/NEW  | HTDA 1576 8M 26   | 197   | 4010858036805   |
| RR1456  | 195HG320 | HTDA 1560 8M 32   | 195   | 4010858036799   |
| RR1062  | NEU/NEW  | HTDA 1656 8M 32   | 207   | 4010858088217   |
| RR1457  | NEU/NEW  | HTDA 1419 9,525M 30 ZZP   | 149   | 4010858036782   |
| RR1063  | 104HP220 | HTDA 991 9,525M 22  | 104   | 4010858088224   |
| RR1064  | 103HP220 | HTDA 981 9,525M 22  | 103   | 4010858088231   |
| RR1065  | NEU/NEW  | HTDA 1496 8M 32   | 187   | 4010858088248   |
| RR1066  | NEU/NEW  | HTDA 1105 9,525M 25 ZZP   | 116   | 4010858088255   |
| RR1067  | NEU/NEW  | HTDA 1229 9,525M 25   | 129   | 4010858088262   |
| RR1068  | NEU/NEW  | STDM 1168 8000 M 24   | 146   | 4010858088279   |
| RR1449  | 198HG240 | STDN 1584 8M 24   | 198   | 4010858140908   |
| RR1069  | NEU/NEW  | STD 1400 8M 29  | 175   | 4010858088286   |
| RR1070  | NEU/NEW  | HTDA 562 9,525M 22  | 59  | 4010858088293   |
| RR1071  | NEU/NEW  | HTDA 1676 9,525M 28   | 176   | 4010858088309   |
| RR1072  | 106HP240 | HTDA 1010 9,525M 24   | 106   | 4010858088316   |
| RR1073  | 137ST220 | STD 1096 8M 22  | 137   | 4010858088323   |
| RR1107  | 120HP300 | HTDA 1143 9,525M 30   | 120   | 4010858088682   |
| RR1108  | 173ST290 | STD 1384 8M 29  | 173   | 4010858036942   |
| RR1109  | 153HP261 | HTDA 1457 9,525M 26 ZZP   | 153   | 4010858088699   |
| RR1110  | 132HP260 | HTDA 1257 9,525M 26 ZZP   | 132   | 4010858088705   |
| RR1453  | 107HG220 | HTDA 856 8M 22  | 107   | 4010858140939   |
| RR1111  | NEU/NEW  | STD 1344 8M 24  | 168   | 4010858088712   |
| RR1112  | 143HP255 | HTDA 1362 9,525M 25   | 143   | 4010858088729   |
| RR1113  | 087TM250 | 326 LAHN 094  | 87  | 4010858035303   |
| RR1114  | NEU/NEW  | HTDA 924 9,525M 19  | 97  | 4010858036676   |
| RR1115  | 122HP290 | HTDA 1162 9,525M 29   | 122   | 4010858088736   |
| RR1116  | 207TM300 | 776 LAHN 118  | 207   | 4010858035310   |

|        |          |                         |     |               |
|--------|----------|-------------------------|-----|---------------|
| RR1117 | 131HP250 | HTDA 1248 9,525M 25     | 131 | 4010858088743 |
| RR1118 | 101HG200 | HTDA 808 8000 M 20      | 101 | 4010858088750 |
| RR1132 | NEU/NEW  | STDN 1544 S8M 24 ZZP    | 193 | 4010858088859 |
| RR1133 | NEU/NEW  | HTDA 1448 9,525M 30     | 152 | 4010858088866 |
| RR1134 | NEU/NEW  | HTDA 1438 9,525M 30     | 151 | 4010858088873 |
| RR1135 | 154HG220 | HTDA 1232 8 M 22        | 154 | 4010858088880 |
| RR1136 | 055TM130 | 206 LAHR 050            | 55  | 4010858035334 |
| RR1137 | NEU/NEW  | STD 1800 8M 30 ZZP      | 225 | 4010858088897 |
| RR1138 | 153HP300 | CPPN 1457 9,525M 30     | 153 | 4010858088903 |
| RR1139 | 141HP254 | CPPN 1343 9,525M 25     | 141 | 4010858088910 |
| RR1140 | 140HP254 | CPPN 1334 9,525M 25     | 140 | 4010858088927 |
| RR1141 | 207TM320 | 776 LAHN 126            | 207 | 4010858035341 |
| RR1142 | 091HP200 | CHDN 867 9,525M 20      | 91  | 4010858088934 |
| RR1143 | 146HP280 | HTDA 1391 9,525 M 28    | 146 | 4010858088941 |
| RR1144 | NEU/NEW  | HTDA 1314 9,525M 23     | 138 | 4010858088958 |
| RR1119 | 137TM230 | 514 LAHR 090            | 137 | 4010858035327 |
| RR1120 | NEU/NEW  | HTDA 1257 9,525 M 28    | 132 | 4010858088767 |
| RR1121 | 109HG250 | HTDA 872 8M 25          | 109 | 4010858088774 |
| RR1122 | NEU/NEW  | HTDA 1276 9,525M 27 ZZP | 134 | 4010858088781 |
| RR1123 | 125HP260 | HTDA 1191 9,525M 26     | 125 | 4010858036744 |
| RR1124 | NEU/NEW  | HTDA 752 9,525M 19 ZZP  | 79  | 4010858088798 |
| RR1125 | NEU/NEW  | HTD 514 9,525M 17       | 54  | 4010858088804 |
| RR1126 | 153HP255 | HTDA 1457 9,525M 25     | 153 | 4010858088811 |
| RR1127 | 112HP240 | HTDA 1067 9,525M 24     | 112 | 4010858036706 |
| RR1128 | 153HP290 | HTDA 1457 9,525M 29     | 153 | 4010858088828 |
| RR1129 | 163ST260 | STD 1304 S8M 26,7       | 163 | 4010858036928 |
| RR1130 | 125HG150 | CPPN 1000 8000 M 15 ZZP | 125 | 4010858088835 |
| RR1131 | 136HP254 | CPPN 1295 9,525M 25     | 136 | 4010858088842 |
| RR1145 | 142HP230 | HTDA 1353 9,525M 23     | 142 | 4010858088965 |
| RR1146 | 129HP254 | HTDA 1229 9,525M 25     | 129 | 4010858088972 |
| RR1147 | 128HP270 | HTDA 1219 9,525M 27     | 128 | 4010858088989 |
| RR1148 | 132HP270 | HTDA 1257 9,525M 27.4   | 132 | 4010858088996 |
| RR1149 | 162ST200 | STD 1296 8M 20          | 162 | 4010858089009 |
| RR1150 | 145HG260 | HTDA 1160 8M 26         | 145 | 4010858089016 |
| RR1151 | 104TP151 | 390 LAN 059 ZZP         | 104 | 4010858035358 |
| RR1152 | 133HG250 | HTDA 1064 8000 M 25     | 133 | 4010858089023 |
| RR1153 | 163HG240 | CPPN 1304 8M 24 ZZP     | 163 | 4010858089030 |
| RR1154 | 153HP254 | HTD 1457 9,525M 25 ZZP  | 153 | 4010858089047 |
| RR1155 | 125SP200 | HTD 1191 9,525M 20      | 125 | 4010858089054 |
| RR1156 |          | (CT 944)                |     | 4010858036379 |
| RR1157 | 136SP254 | CPPN 1295 9,525M 25     | 136 | 4010858089061 |
| RR1158 | 112HP280 | CPPN 1067 9,525M 28     | 112 | 4010858089078 |
| RR1159 | 118HP300 | CPPN 1124 9,525 M 30    | 118 | 4010858036546 |
| RR1160 | 147HP320 | CPPN 1400 9,525 M 32    | 147 | 4010858089085 |
| RR1161 | 078HP220 | CPPN 743 9,525 M 22     | 78  | 4010858089092 |
| RR1162 | 151HP254 | HTDA 1438 9,525M 25 ZZP | 151 | 4010858089108 |
| RR1163 | 166HG240 | STDN 1328 S8M 24 ZZP    | 166 | 4010858089115 |
| RR1164 | 141TM250 | 529 LAHR 100            | 141 | 4010858035365 |
| RR1165 | 137TP254 | 514 LAHR 100            | 137 | 4010858035372 |
| RR1166 | 105HP220 | HTDA 1000 9,525M 22     | 105 | 4010858089122 |

|        |              |                          |     |               |
|--------|--------------|--------------------------|-----|---------------|
| RR1167 | 154HG290     | HTDA 1232 8 M 29         | 154 | 4010858089139 |
| RR1081 | NEU/NEW      | 529 LAHR 9,525 M 102     | 141 | 4010858088415 |
| RR1074 | NEU/NEW      | STD 2248 8M 30           | 281 | 4010858088330 |
| RR1075 | 104SP171     | HTD 991 9,525M 17 ZZP    | 104 | 4010858088347 |
| RR1076 | 100HP170     | HTD 952 9,525M 17        | 100 | 4010858088354 |
| RR1077 | 134HP255     | HTDA 1276 9,525M 26 ZZP  | 134 | 4010858088361 |
| RR1078 | NEU/NEW      | HTDA 1267 9,525M 26 ZZP  | 133 | 4010858088378 |
| RR1079 | 144HP254     | CPPN 1372 9,525M 25      | 144 | 4010858088385 |
| RR1080 | 110ST220     | STD 880 8000 M 22        | 110 | 4010858088392 |
| RR1004 | 136SP/CP254  | HTD 1295 9,525M 25       | 136 | 4010858087685 |
| RR1082 | NEU/NEW      | HTDA 2248 8M 30 ZZP      | 281 | 4010858088446 |
| RR1083 | 178HP300     | CPPN 1695 9,525M 30 ZZP  | 178 | 4010858088453 |
| RR1084 | NEU/NEW      | STD 1160 8000 M 23       | 145 | 4010858088460 |
| RR1085 | NEU/NEW      | CHDN 1238 9,525M 28      | 130 | 4010858088477 |
| RR1450 | 130TP254     | CHDN 1238 9,525M 25      | 130 | 4010858140915 |
| RR1086 | 111HG290     | HTDA 888 8000 M 29       | 111 | 4010858088484 |
| RR1451 | 259ST320     | STDN 2072 S8M 32         | 259 | 4010858037000 |
| RR1087 | NEU/NEW      | HTDA 1343 9,525M 30      | 141 | 4010858088491 |
| RR1088 | NEU/NEW      | HTDA 1784 8M 27 ZZP      | 223 | 4010858088507 |
| RR1089 | 124HG220     | CPPN 992 8M 22           | 124 | 4010858088514 |
| RR1090 | 116HG290     | HTDA 928 8M 29 EV        | 116 | 4010858088521 |
| RR1091 | NEU/NEW      | HTDA 984 8000 M 22       | 123 | 4010858088538 |
| RR1092 | 089HP250     | CPPN 848 9,525M 25       | 89  | 4010858088545 |
| RR1093 | 095HP234     | HTDA 905 9,525M 23,4 ZZP | 95  | 4010858088552 |
| RR1094 | 141TM251     | 529 LAHR 100             | 141 | 4010858035297 |
| RR1095 | 178HP250     | HTD 1695 9,525M 25       | 178 | 4010858088569 |
| RR1096 | 078HP240     | CPPN 743 9,525 M 24      | 78  | 4010858088576 |
| RR1097 | 112HP300     | CPPN 1067 9,525M 30      | 112 | 4010858088583 |
| RR1098 | 126HP270     | HTDA 1200 9,525M 27      | 126 | 4010858088590 |
| RR1452 | 152HP300     | CHDN 1448 9,525M 30      | 152 | 4010858140922 |
| RR1099 | 146HP254     | CPPN 1391 9,525M 25      | 146 | 4010858088606 |
| RR1100 | 153HP270     | HTDA 1457 9,525M 27      | 153 | 4010858088613 |
| RR1101 | 123HP270     | HTDA 1172 9,525M 27 ZZP  | 123 | 4010858088620 |
| RR1102 | 154HP300     | CPPN 1467 9,525M 30      | 154 | 4010858088637 |
| RR1103 |              | HTDA 1267 9,525M 25 ZZP  | 133 | 4010858088644 |
| RR1104 | 136SP/HP254  | HTD 1295 9,525M 25       | 136 | 4010858088651 |
| RR1105 | NEU/NEW      | HTDA 1024 8000 M 26      | 128 | 4010858088668 |
| RR1106 | 211HG320     | HTDK 1688 8M 32 ZZP      | 211 | 4010858088675 |
| RR1168 | 153HP260     | HTDA 1457 9,525M 26 ZZP  | 153 | 4010858089146 |
| RR1169 | 122TM265/254 | 457 LAHR 104             | 122 | 4010858036249 |
| RR1170 | 113HP254     | HTDA 1076 9,525M 25,5    | 113 | 4010858089153 |
| RR1171 | 091HP190     | HTDA 867 9,525 M 19 ZZP  | 91  | 4010858089160 |
| RR1172 | NEU/NEW      | HTDA 1457 9,525M 25 ZZP  | 153 | 4010858089177 |
| RR1173 | 076TM190     | 285 LAH 075 ZZP          | 76  | 4010858035389 |
| RR1174 | NEU/NEW      | HTDA 791 9,525M 19       | 83  | 4010858089207 |
| RR1175 | 173HG180     | STDN 1384 S8M 18         | 173 | 4010858089214 |
| RR1176 | 143HG260     | HTDA 1144 8M 26          | 143 | 4010858089221 |
| RR1177 | 108SP150     | 405 LAN 059 ZZP          | 108 | 4010858035396 |
| RR1178 | 147ST190     | STD 1176 S8M 19          | 147 | 4010858089252 |
| RR1179 | 171HG240     | STD 1368 S8M 24          | 171 | 4010858089269 |

|        |             |                         |     |               |
|--------|-------------|-------------------------|-----|---------------|
| RR1180 | 253HG300    | STD 2024 S8M 30         | 253 | 4010858036997 |
| RR1181 | 153ST250    | STD 1224 8000 M 25      | 153 | 4010858089276 |
| RR1182 | 193HG240    | STDN 1544 S8M 24 ZZP    | 193 | 4010858089283 |
| RR1183 | 117HP254    | HTDA 1114 9,525M 25 ZZP | 117 | 4010858089290 |
| RR1184 | 081TM210    | 304 LAHR 082            | 81  | 4010858036409 |
| RR1185 | 122HP190    | HTDA 1162 9,525M 19     | 122 | 4010858089306 |
| RR1186 | 150ST230    | STDH 1200 8000 M 23     | 150 | 4010858089313 |
| RR1187 | 138ST230    | STD 1104 S8M 23         | 138 | 4010858036904 |
| RR1188 | 149ST250    | STD 1192 S8M 25         | 149 | 4010858089320 |
| RR1189 | NEU/NEW     | HTD 1295 9,525M 25 ZZP  | 136 | 4010858032265 |
| RR1190 | 152HP280    | HTDA 1448 9,525M 28     | 152 | 4010858089337 |
| RR1191 |             | (CT 883)                |     | 4010858036331 |
| RR1192 | 125HG220    | HTDA 1000 8000 M 22     | 125 | 4010858089344 |
| RR1193 | 089HP254    | HTDA 848 9,525M 25      | 89  | 4010858089351 |
| RR1194 | 143TM300    | 536 LAH 118 ZZP         | 143 | 4010858035402 |
| RR1195 | 097HP254    | HTDA 924 9,525M 25      | 97  | 4010858036683 |
| RR1196 | 193HG360    | STD 1544 S8M 36 ZZP     | 193 | 4010858089368 |
| RR1197 | 196HP280    | HTDA 1867 9,525M 28     | 196 | 4010858036836 |
| RR1198 | 127HP250    | HTDA 1210 9,525M 25     | 127 | 4010858089375 |
| RR1199 | 225HG/ST300 | STD 1800 S8M 30 ZZP     | 225 | 4010858089382 |
| RR1200 | 167HG240    | STDN 1336 8M 24 ZZP     | 167 | 4010858089399 |
| RR1201 | 158HG250    | STDN 1264 S8M 25        | 158 | 4010858036348 |
| RR1202 | 134HG180    | STDN 1072 8000 M 18 ZZP | 134 | 4010858089405 |
| RR1203 | 168HG240    | STDN 1344 8M 24 ZZP     | 168 | 4010858089412 |
| RR1204 | NEU/NEW     | HTDK 1032 8M 27         | 129 | 4010858089429 |
| RR1205 | 111HP170    | HTD 1057 9,525M 17      | 111 | 4010858036270 |
| RR1206 | 169HG200    | STD 1352 S8M 20         | 169 | 4010858036294 |
| RR1207 | 151ST250    | STD 1208 S8M 25         | 151 | 4010858089436 |
| RR1208 | 176HG240    | STD 1408 S8M 24         | 176 | 4010858036966 |
| RR1209 | 169HG240    | STD 1352 S8M 24         | 169 | 4010858036935 |
| RR1210 | 147ST250    | STD 1176 S8M 25         | 147 | 4010858089443 |
| RR1211 | 137TM254    | 514 LAHR 100            | 137 | 4010858036522 |
| RR1212 | 146HG200    | STD 1168 8M 20          | 146 | 4010858036911 |
| RR1213 | 114HP254    | HTD 1086 9,525M 25 ZZP  | 114 | 4010858089450 |
| RR1214 | 134HP254    | HTD 1276 9,525M 25 ZZP  | 134 | 4010858089467 |
| RR1215 | 104HP240    | HTDA 991 9,525M 24      | 104 | 4010858089474 |
| RR1216 | 103HP240    | HTDA 981 9,525M 24      | 103 | 4010858089481 |
| RR1217 | 095TM190    | 356 LAHN 075            | 95  | 4010858035419 |
| RR1218 | 102HP250    | HTD 972 9,525M 25 ZZP   | 102 | 4010858089498 |
| RR1219 | 179HG320    | STD 1432 8M 32 ZZP      | 179 | 4010858089504 |
| RR1220 | NEU/NEW     | HTDA 856 8M 18          | 107 | 4010858089511 |
| RR1221 | 107HG160    | HTDA 856 8M 16          | 107 | 4010858089528 |
| RR1222 | 144HP230    | HTDA 1372 9,525M 23     | 144 | 4010858089535 |
| RR1223 | 139HP210    | HTDA 1324 9,525M 21     | 139 | 4010858089542 |
| RR1224 | 157HP254    | HTDA 1495 9,525M 25 ZZP | 157 | 4010858089559 |
| RR1225 | 191HG320    | STD 1528 8M 32 ZZP      | 191 | 4010858036973 |
| RR1226 | 121HG211    | HTDK 968 8M 21          | 121 | 4010858089566 |
| RR1227 | 152HG250    | STD 1216 S8M 25         | 152 | 4010858089573 |
| RR1228 | 121TP181    | 454 LAN 071             | 121 | 4010858036485 |
| RR1229 | 137HG190    | STD 1096 8M 19          | 137 | 4010858089580 |

|        |             |                         |     |               |
|--------|-------------|-------------------------|-----|---------------|
| RR1230 | 132ST190    | STD 1056 8000 M 19      | 132 | 4010858089597 |
| RR1231 | 223HG320    | STD 1784 S8M 32 ZZP     | 223 | 4010858036980 |
| RR1232 | 141TM300    | 529 LAHR 118 ZZP        | 141 | 4010858035426 |
| RR1233 | 158HP320    | HTDA 1505 9,525M 32     | 158 | 4010858089603 |
| RR1234 | 117HG290    | HTDA 936 8M 29          | 117 | 4010858089610 |
| RR1235 | 127HP190    | HTD 1210 9,525M 19 ZZP  | 127 | 4010858089627 |
| RR1236 | 123HP290    | HTDA 1172 9,525M 29     | 123 | 4010858089634 |
| RR1237 | NEU/NEW     | STD 1760 S8M 22         | 220 | 4010858089641 |
| RR1238 | 124HP290    | HTDA 1181 9,525M 29     | 124 | 4010858036317 |
| RR1239 | NEU/NEW     | HTDK 800 8M 19          | 100 | 4010858089658 |
| RR1240 | NEU/NEW     | HTDK 792 8M 16 ZZP      | 99  | 4010858089665 |
| RR1241 | 162ST254    | STD 1296 8M 25          | 162 | 4010858089672 |
| RR1242 | 192ST300    | STD 1536 S8M 30         | 192 | 4010858089689 |
| RR1243 | 124HG260    | HTDK 992 8M 26          | 124 | 4010858089696 |
| RR1244 | 117HG211    | HTDK 936 8M 21          | 117 | 4010858089887 |
| RR1245 | 151HP290    | HTDA 1438 9,525M 29     | 151 | 4010858089719 |
| RR1246 | 123HP190    | HTDA 1172 9,525M 19 ZZP | 123 | 4010858089726 |
| RR1247 | 089HP190    | HTDA 848 9,525M 19 ZZP  | 89  | 4010858089733 |
| RR1248 | 257HG320    | HTDA 2056 8M 32         | 257 | 4010858089740 |
| RR1249 | 121HG290    | HTDA 968 8M 29          | 121 | 4010858089757 |
| RR1250 | 173ST300    | STD 1384 8M 30          | 173 | 4010858036959 |
| RR1251 | 134HP250    | HTD 1276 9,525M 25      | 134 | 4010858089764 |
| RR1252 | 137ST254    | STD 1096 8M 25          | 137 | 4010858089771 |
| RR1253 | 192HP280    | HTDA 1829 9,525M 28     | 192 | 4010858036829 |
| RR1254 | 156HG290    | HTDA 1248 8M 29         | 156 | 4010858089788 |
| RR1255 | NEU/NEW     | HTDA 1029 9,525M 32 ZZP | 108 | 4010858089795 |
| RR1256 | 095HP190    | HTDA 905 9,525M 19      | 95  | 4010858089801 |
| RR1257 | 149HP255    | HTDA 1419 9,525M 25     | 149 | 4010858036775 |
| RR1258 | 127HP/HG240 | HTDA 1210 9,525M 24     | 127 | 4010858089818 |
| RR1259 | NEU/NEW     | HTD 1257 9,525M 23      | 132 | 4010858089825 |
| RR1260 | 122HP240    | HTDA 1162 9,525M 24     | 122 | 4010858089832 |
| RR1261 | 123TM190    | 461 LAHR 075            | 123 | 4010858035433 |
| RR1262 | 070HP160    | HTDA 667 9,525M 16      | 70  | 4010858089856 |
| RR1263 | 113HP240    | HTDA 1076 9,525M 24     | 113 | 4010858089863 |
| RR1264 | 119HP254    | HTDA 1133 9,525M 25     | 119 | 4010858089870 |
| RR1265 | 124HP260    | HTDA 1181 9,525M 26     | 124 | 4010858036737 |
| RR1266 | 119HP254    | HTDA 1133 9,525M 25     | 119 | 4010858089894 |
| RR1267 | 211HG300    | HTDA 1688 8M 30 ZZP     | 211 | 4010858036812 |
| RR1268 | 080TM210    | 300 LAHN 083            | 80  | 4010858089900 |
| RR1269 | 168HG254    | HTDA 1344 8M 25         | 168 | 4010858089917 |
| RR1270 | 119HP190    | HTDA 1133 9,525M 19     | 119 | 4010858089924 |
| RR1271 | 095HP250    | HTDA 905 9,525M 25 ZZP  | 95  | 4010858089931 |
| RR1272 | 135HG250    | HTDA 1080 8000 M 25     | 135 | 4010858036713 |
| RR1273 | NEU/NEW     | 559 LAHR 118 ZZP        | 149 | 4010858035440 |
| RR1274 | 104HP254    | HTDA 991 9,525M 25      | 104 | 4010858089948 |
| RR1275 | 178HG/HT254 | HTDK 1424 8M 25         | 178 | 4010858089955 |
| RR1276 | 121HP200    | HTD 1153 9,525M 20      | 121 | 4010858089962 |
| RR1277 | 098HP/SP190 | STD 933 9,525M 19       | 98  | 4010858036898 |
| RR1278 | 119HP/SP190 | STD 1133 9,525M 19      | 119 | 4010858036881 |
| RR1279 | 144HP/CP250 | HTD 1372 9,525M 25      | 144 | 4010858089979 |

|        |             |                         |     |               |
|--------|-------------|-------------------------|-----|---------------|
| RR1280 | 110HP254    | HTDA 1048 9,525M 25     | 110 | 4010858036690 |
| RR1281 | 124HP240    | HTDA 1181 9,525M 24     | 124 | 4010858036720 |
| RR1282 | 149HP254    | HTD 1419 9,525M 25      | 149 | 4010858036645 |
| RR1283 | 139TP180    | 521 LA 071              | 139 | 4010858035457 |
| RR1284 | 145HG220    | HTDA 1160 8M 22         | 145 | 4010858089986 |
| RR1285 | 145HG220    | HTDK 1160 8000 M 21,6   | 145 | 4010858089993 |
| RR1286 | 103HP190    | HTDA 981 9,525M 19 ZZP  | 103 | 4010858140007 |
| RR1287 | 108HP254    | HTDA 1029 9,525M 25     | 108 | 4010858140014 |
| RR1288 | 107SP/CP240 | HTDA 1019 9,525M 24     | 107 | 4010858140021 |
| RR1289 | 162ST300    | STD 1296 8M 30          | 162 | 4010858140038 |
| RR1290 | 148HP255    | HTDA 1410 9,525M 25 ZZP | 148 | 4010858140045 |
| RR1291 | 148HP230    | HTDA 1410 9,525M 23     | 148 | 4010858140052 |
| RR1292 | 120TM254    | 450 LAHN 100            | 120 | 4010858035464 |
| RR1293 | 103HP254    | HTDA 981 9,525M 25      | 103 | 4010858140069 |
| RR1294 | 124TM265    | 465 LAHN 104            | 124 | 4010858035471 |
| RR1295 | 118HP/SP190 | HTD 1124 9,525M 19 ZZP  | 118 | 4010858140076 |
| RR1296 | 116HP190    | HTD 1105 9,525M 19 ZZP  | 116 | 4010858140083 |
| RR1297 | NEU/NEW     | STD 920 S8M 25 ZZP      | 115 | 4010858140090 |
| RR1298 | 110HG190    | HTDA 880 8000 M 19      | 110 | 4010858140106 |
| RR1299 | 101HP170    | HTD 962 9,525M 17 ZZP   | 101 | 4010858036287 |
| RR1300 | 107HG190    | HTDA 856 8M 19          | 107 | 4010858140113 |
| RR1301 | 093HP254    | HTDA 886 9,525M 25 ZZP  | 93  | 4010858140120 |
| RR1302 | 091HP190    | HTDA 867 9,525 M 19 ZZP | 91  | 4010858036669 |
| RR1303 | 143HP210    | HTDA 1362 9,525M 21     | 143 | 4010858140137 |
| RR1304 | 133ST190    | STD 1064 8000 M 19      | 133 | 4010858140144 |
| RR1305 | 152TM300    | 570 LAH 118             | 152 | 4010858035488 |
| RR1306 | 097HP216    | HTDN 924 9,525M 21,8    | 97  | 4010858036850 |
| RR1307 | 299ST300    | STD 2392 8M 30          | 299 | 4010858140168 |
| RR1308 | 239HG254    | STD 1912 S8M 25         | 239 | 4010858140175 |
| RR1309 | 141HP240    | HTDH 1343 9,525M 24     | 141 | 4010858140182 |
| RR1310 | 129HP/CP240 | HTD 1229 9,525M 24      | 129 | 4010858140199 |
| RR1311 | 143TM300    | 536 LAH 118             | 143 | 4010858035495 |
| RR1312 | 111HP/CP200 | HTDH 1057 9,525M 20     | 111 | 4010858036843 |
| RR1313 | NEU/NEW     | 480 H 075               | 96  | 4010858035501 |
| RR1314 | 115TP190    | 431 LA 075              | 115 | 4010858035518 |
| RR1315 | 092TM190    | 345 LAHR 075            | 92  | 4010858035525 |
| RR1316 | 083TM190    | 311 LAHR 075            | 83  | 4010858035532 |
| RR1317 | 164HP230    | HTDN 1562 9,525M 23 ZZP | 164 | 4010858140205 |
| RR1318 | 151HP254    | HTD 1438 9,525M 25 ZZP  | 151 | 4010858140212 |
| RR1319 | 143HP254    | HTD 1362 9,525M 25 ZZP  | 143 | 4010858140229 |
| RR1320 | 143HG230    | HTDA 1144 8M 23         | 143 | 4010858140236 |
| RR1321 | 126HG230    | HTDA 1008 8000 M 23     | 126 | 4010858140243 |
| RR1322 | 121HG240    | HTDK 968 8M 24          | 121 | 4010858140250 |
| RR1323 | 121HG200    | HTDK 968 8M 20          | 121 | 4010858140267 |
| RR1324 | 119TM254    | 446 LAH 100             | 119 | 4010858036454 |
| RR1325 | 099TM190    | 371 LAH 075             | 99  | 4010858035549 |
| RR1326 | 118TP150    | 443 LA 059              | 118 | 4010858035556 |
| RR1327 | 118TM320    | 443 LAH 125 ZZP         | 118 | 4010858035563 |
| RR1328 | 102TP205    | 383 LA 081              | 102 | 4010858035570 |
| RR1329 | 046TP190    | 173 LA 075              | 46  | 4010858035587 |

|        |             |                       |     |               |
|--------|-------------|-----------------------|-----|---------------|
| RR1330 | 123HG240    | HTDK 984 8M 24        | 123 | 4010858140274 |
| RR1331 | 123HG200    | HTDK 984 8M 20        | 123 | 4010858140281 |
| RR1332 | 133TP254    | 499 LA 100 ZZP        | 133 | 4010858036256 |
| RR1333 | NEU/NEW     | 514 LA 100 EV         | 137 | 4010858035594 |
| RR1334 | 092HP/CP198 | HTDN 876 9,525M 19,75 | 92  | 4010858140298 |
| RR1335 | 119TP190    | 446 LAR 075           | 119 | 4010858035600 |
| RR1336 | 149TM300    | 559 LAH 118           | 149 | 4010858035617 |
| RR1337 | 088TP190    | 330 LA 075            | 88  | 4010858036416 |
| RR1338 | 102TP190    | 383 LA 075            | 102 | 4010858035624 |
| RR1339 | 138TP254    | 518 LA 100            | 138 | 4010858035631 |
| RR1340 | 133TP220    | 499 LA 087            | 133 | 4010858036508 |
| RR1341 | 118TP190    | 443 LA 075 ZZP        | 118 | 4010858035648 |
| RR1342 | 103TP190    | 386 LA 075 ZZP        | 103 | 4010858035655 |
| RR1343 | 095TP190    | 356 LA 075 ZZP        | 95  | 4010858035662 |
| RR1344 | 091TP190    | 341 LA 075 ZZP        | 91  | 4010858035679 |
| RR1345 | 090TP190    | 338 LA 075 ZZP        | 90  | 4010858035686 |
| RR1346 | 138TP180    | 518 LA 071            | 138 | 4010858035693 |
| RR1347 | 084TP190    | 315 LA 075            | 84  | 4010858035709 |
| RR1348 | 069TP190    | 259 LA 075 ZZP        | 69  | 4010858035716 |
| RR1349 | 068TP150    | 255 LA 059            | 68  | 4010858035723 |
| RR1350 | 106TP190    | 398 LA 075            | 106 | 4010858036447 |
| RR1351 | 092TP190    | 345 LA 075            | 92  | 4010858035730 |
| RR1352 | 055TP127    | 206 LA 050            | 55  | 4010858035747 |
| RR1353 | 123TM254    | 461 LAH 100           | 123 | 4010858035754 |
| RR1354 | 062TM190    | 232 LAH 075           | 62  | 4010858035761 |
| RR1355 | 120TP180    | 450 LA 071            | 120 | 4010858036478 |
| RR1356 | 105TP190    | 394 LA 075 ZZP        | 105 | 4010858035778 |
| RR1357 | 098TP190    | 367 LA 075 ZZP        | 98  | 4010858035785 |
| RR1358 | 098TP170    | 367 LA 067            | 98  | 4010858035792 |
| RR1359 | 093TP190    | 349 LA 075 ZZP        | 93  | 4010858035808 |
| RR1360 | 148TP190    | 555 LA 075            | 148 | 4010858035815 |
| RR1361 | 144TP190    | 540 LA 075            | 144 | 4010858035822 |
| RR1362 | 117TP150    | 439 LA 059            | 117 | 4010858035839 |
| RR1363 | 146TP190    | 547 LA 075            | 146 | 4010858035846 |
| RR1364 | 054TP190    | 202 LA 075            | 54  | 4010858035853 |
| RR1365 | 077TM200    | 289 LAHN 079          | 77  | 4010858035860 |
| RR1366 | 123TP190    | 461 LA 075 ZZP        | 123 | 4010858036492 |
| RR1367 | 075TM200    | 281 LAH 079           | 75  | 4010858035877 |
| RR1368 | 045TP102    | 169 LA 040            | 45  | 4010858035884 |
| RR1369 | 113TP190    | 424 LA 075            | 113 | 4010858035891 |
| RR1370 | 120TP190    | 450 LA 075            | 120 | 4010858035907 |
| RR1371 | 124TP180    | 465 LAN 071           | 124 | 4010858036300 |
| RR1372 | 107HP240    | HTD 1019 9,525M 24    | 107 | 4010858140304 |
| RR1373 | 120TP150    | 450 LA 059            | 120 | 4010858035914 |
| RR1374 | 153TM300    | 574 LAH 118           | 153 | 4010858035921 |
| RR1375 | 173ST254    | STDN 1384 S8M 25      | 173 | 4010858140311 |
| RR1376 | 173HG220    | STDN 1384 S8M 22      | 173 | 4010858140328 |
| RR1377 | 098TM190    | 367 LAH 075           | 98  | 4010858035938 |
| RR1378 | 170HG220    | STDN 1360 S8M 22      | 170 | 4010858140335 |
| RR1379 | 117TM254    | 439 LAH 100 ZZP       | 117 | 4010858035945 |

|        |                |                          |     |               |
|--------|----------------|--------------------------|-----|---------------|
| RR1380 | 170ST254       | STDN 1360 S8M 25         | 170 | 4010858140342 |
| RR1381 | 087TM340       | 326 LAH 133              | 87  | 4010858035952 |
| RR1382 | 142TP254       | 533 LA 100               | 142 | 4010858035969 |
| RR1383 | 165ST220       | STDN 1320 S8M 22         | 165 | 4010858140359 |
| RR1384 | 142TP180       | 533 LA 071               | 142 | 4010858035976 |
| RR1385 | 108HP170       | HTD 1029 9,525M 17 ZZP   | 108 | 4010858140366 |
| RR1386 | 138HG150       | STDN 1104 8000 M 15 ZZP  | 138 | 4010858140373 |
| RR1387 | 107HG216       | HTDK 856 8M 21,6         | 107 | 4010858140380 |
| RR1388 | 107HG190       | HTDK 856 8M 19           | 107 | 4010858140397 |
| RR1389 | 127TP254       | 476 LA 100               | 127 | 4010858035983 |
| RR1390 | 219TM254       | 821 LAH 100              | 219 | 4010858035990 |
| RR1391 | 143TP254       | 536 LA 100               | 143 | 4010858036003 |
| RR1392 | 143TP190       | 536 LA 075               | 143 | 4010858036010 |
| RR1393 | 109TP190       | 409 LA 075               | 109 | 4010858036027 |
| RR1394 | 118TP190       | 443 LA 075               | 118 | 4010858036034 |
| RR1395 | 152ST250       | STD 1216 S8M 25          | 152 | 4010858140403 |
| RR1396 | 148ST254       | STD 1184 8M 25           | 148 | 4010858140410 |
| RR1397 | 127CP250       | HTD 1210 9,525M 25       | 127 | 4010858140427 |
| RR1398 | 110HP210       | HTD 1048 9,525M 21       | 110 | 4010858140434 |
| RR1399 | 168ST180       | STDN 1344 8M 18          | 168 | 4010858140441 |
| RR1400 | 109HP/CP220    | HTD 1038 9,525M 22       | 109 | 4010858140458 |
| RR1401 | 106HP/CP220    | HTD 1010 9,525M 22       | 106 | 4010858140465 |
| RR1402 | 219HP/CP254    | HTD 2086 9,525M 25       | 219 | 4010858140472 |
| RR1403 | 177HP/CP254    | HTD 1686 9,525M 25       | 177 | 4010858140489 |
| RR1404 | 100TP170       | 375 LA 067               | 100 | 4010858036041 |
| RR1405 | 093TP190       | 349 LA 075               | 93  | 4010858036058 |
| RR1406 | 139TP254       | 521 LA 100               | 139 | 4010858036065 |
| RR1407 | 097TP254       | 364 LA 100               | 97  | 4010858036072 |
| RR1408 | 110TP254       | 413 LA 100               | 110 | 4010858036089 |
| RR1409 | 110TP180       | 413 LA 071               | 110 | 4010858036096 |
| RR1410 | 097TP190       | 364 LA 075               | 97  | 4010858036102 |
| RR1411 | 089TP190       | 334 LA 075               | 89  | 4010858036119 |
| RR1412 | 091TP190       | 341 LA 075               | 91  | 4010858036126 |
| RR1413 | NEU/NEW        | 300 L 063                | 80  | 4010858036133 |
| RR1414 | 108HP/CP240    | HTD 1029 9,525M 24       | 108 | 4010858140496 |
| RR1415 | 112HP/CP190    | HTD 1067 9,525M 19       | 112 | 4010858140502 |
| RR1416 | 113HP/CP190    | HTD 1076 9,525M 19       | 113 | 4010858140519 |
| RR1417 | 124HP190       | HTD 1181 9,525M 19 ZZP   | 124 | 4010858140526 |
| RR1418 | 128ST250/HG254 | STD 1024 S8M 25          | 128 | 4010858140533 |
| RR1419 | 110HP/CP170    | HTD 1048 9,525M 17       | 110 | 4010858140540 |
| RR1420 | 071HK/CP178    | HTD/KRR 676 9,525 M 17,8 | 71  | 4010858140557 |
| RR1421 | 101HP/CP240    | HTD 962 9,525M 24        | 101 | 4010858036621 |
| RR1422 | 157HP/CP320    | HTD 1495 9,525M 32       | 157 | 4010858140564 |
| RR1423 | 141TP254       | 529 LA 100               | 141 | 4010858036140 |
| RR1424 | 157HP/CP230    | HTD 1495 9,525M 23       | 157 | 4010858140571 |
| RR1425 | 126TP254       | 473 LA 100               | 126 | 4010858036157 |
| RR1426 | 057TP190       | 214 LA 075               | 57  | 4010858036164 |
| RR1427 | 142ST190       | STD 1136 S8M 19          | 142 | 4010858140588 |
| RR1428 | 109HP/CP190    | HTD 1038 9,525M 19       | 109 | 4010858140595 |
| RR1429 | 107HP/CP200    | HTD 1019 9,525M 20       | 107 | 4010858140601 |

|        |              |                           |     |               |
|--------|--------------|---------------------------|-----|---------------|
| RR1430 | 106HP/CP190  | HTD 1010 9,525M 19        | 106 | 4010858140618 |
| RR1431 | 164ST250     | STD 1312 S8M 25           | 164 | 4010858140625 |
| RR1432 | 138HK/CP285  | HTD/KRR 1314 9,525 M 28,5 | 138 | 4010858140632 |
| RR1433 | 128CM254     | HTD 1052 8,22M 25         | 128 | 4010858140649 |
| RR1434 | 111HP190/191 | HTDN 1057 9,525M 19       | 111 | 4010858036867 |
| RR1435 | 101CP/HP170  | HTD 962 9,525M 17         | 101 | 4010858036614 |
| RR1436 | 113CP/HP170  | HTD 1076 9,525M 17 ZZP    | 113 | 4010858140656 |
| RR1437 | 117CP/HP190  | HTD 1114 9,525M 19        | 117 | 4010858140663 |
| RR1438 | 130HP254     | HTD 1238 9,525M 25        | 130 | 4010858140670 |
| RR1439 | 127CM254     | HTD 1044 8,220 M 25       | 127 | 4010858036638 |
| RR1440 | 137TM300     | 514 LAHR 118              | 137 | 4010858036171 |
| RR1441 | 151ST190     | STD 1208 S8M 19 ZZP       | 151 | 4010858140687 |
| RR1442 | 122TM190     | 457 LAHR 075              | 122 | 4010858036188 |
| RR1443 | 120TM190     | 450 LAHR 075              | 120 | 4010858036195 |
| RR1444 | 119TM320     | 446 LAH 126               | 119 | 4010858036461 |
| RR1445 | 104TP254     | 390 LA 100                | 104 | 4010858036201 |
| RR1446 | 104TP170     | 390 LA 067                | 104 | 4010858036218 |
| RR1447 | 104TP151     | 390 LA 059 ZZP            | 104 | 4010858036362 |
| RR1448 | 104TP150     | 390 LA 059                | 104 | 4010858036324 |
| RR1001 | 116TP190     | 435 LA 075 ZZP            | 116 | 4010858034986 |
| RR1002 | 135TM250     | 506 LAHN 100              | 135 | 4010858034993 |
| RR1003 | 121TP180     | 454 LA 071                | 121 | 4010858035006 |
| RR1005 | 095HP170     | HTD 905 9,525M 17 ZZP     | 95  | 4010858087692 |
| RR1006 | 104HP170     | HTD 991 9,525M 17         | 104 | 4010858087708 |
| RR1007 | 168ST220     | STDN 1344 8M 22           | 168 | 4010858087715 |
| RR1008 | 108TP190     | 405 LA 075                | 108 | 4010858035013 |
| RR1009 | 146HP/CP240  | HTD 1391 9,525M 24        | 146 | 4010858087722 |
| RR1010 | 147CP/HP240  | HTD 1400 9,525M 24        | 147 | 4010858087739 |
| RR1011 | 122TP190     | 457 LAR 075               | 122 | 4010858035020 |
| RR1012 | 104SP/HP170  | HTD 991 9,525M 17 ZZP     | 104 | 4010858087746 |
| RR1013 | 153HP254     | HTD 1457 9,525M 25 ZZP    | 153 | 4010858087753 |
| RR1014 | 087HP170     | HTD 829 9,525M 17 ZZP     | 87  | 4010858087760 |
| RR1015 | 129ST150     | CPPN 1032 8000 M 15 ZZP   | 129 | 4010858087777 |
| RR1016 | 136TM254     | 510 LAH 100               | 136 | 4010858035037 |
| RR1017 | 148HP254     | HTD 1410 9,525M 25 ZZP    | 148 | 4010858087784 |
| RR1018 | 117HP220     | HTDA 1114 9,525M 22       | 117 | 4010858087791 |
| RR1019 | 097HP/CP198  | HTDN 924 9,525M 19,75     | 97  | 4010858087807 |
| RR1020 | 135ST190     | STD 1080 S8M 19           | 135 | 4010858087814 |
| RR1021 | 128ST190     | STD 1024 S8M 19           | 128 | 4010858087821 |
| RR1022 | 125HP190     | HTD 1191 9,525M 19 ZZP    | 125 | 4010858087838 |
| RR1023 | 094TP190     | 352 LA 075                | 94  | 4010858035259 |
| RR1024 | 129HP310     | HTD 1229 9,525M 31        | 129 | 4010858087845 |
| RR1026 | 131HP254     | HTDA 1248 9,525M 25       | 131 | 4010858087890 |
| RR1027 | 153TM254     | 574 LAH 100 ZZP           | 153 | 4010858035266 |
| RR1029 | 114HP170     | HTD 1086 9,525M 17        | 114 | 4010858087883 |
| RR1030 | 130TM254     | 487 LAH 100               | 130 | 4010858035273 |
| RR1031 | 092HP220     | HTDA 876 9,525M 22        | 92  | 4010858087906 |
| RR1032 | 163HP254     | HTDA 1553 9,525M 25 ZZP   | 163 | 4010858087913 |
| RR1034 | 163TM254     | 611 LAHR 100              | 163 | 4010858035280 |
| RR1035 | 096HP170     | HTD 914 9,525M 17 ZZP     | 96  | 4010858087937 |

|        |          |                         |     |               |
|--------|----------|-------------------------|-----|---------------|
| RR1037 | 111HP254 | HTDA 1057 9,525M 25 ZZP | 111 | 4010858087951 |
| RR1038 | 141HP280 | HTD 1343 9,525M 28      | 141 | 4010858087968 |
| RR1039 | 190HG240 | CPPN 1520 8M 24 ZZP     | 190 | 4010858087975 |
| RR1458 | 107HG254 | HTDA 856 8M 25          | 107 | 4010858036652 |
| RR1459 | 145HP300 | HTDA 1381 9,525M 30 ZZP | 145 | 4010858036751 |
| RR1460 | 135HP254 | CPPN 1286 9,525M 25,4   | 135 | 4010858036553 |
| RR1461 | 134TP254 | 503 LA 100              | 134 | 4010858036515 |
| RR1462 | 176HP280 | CPPN 1676 9,525M 28     | 176 | 4010858036560 |
| RR1463 | 096TM254 | 360 LAH 100             | 96  | 4010858036423 |
| RR1464 | 109HP300 | CPPN 1038 9,525 M 30    | 109 | 4010858036539 |
| RR1465 | 167HP230 | HTDN 1591 9,525M 23     | 167 | 4010858036874 |
| RR1466 | 078HP190 | HTD 743 9,525M 19 ZZP   | 78  | 4010858036591 |
| RR1467 | 044TP170 | kein Conti              | 44  | 4010858037055 |
| RR1468 | 126HP260 | HTDA 1200 9,525 M 26    | 126 | 4010858037062 |
| RR1469 | 097TM150 | 364 DLAH 059            | 97  | 4010858036430 |
| RR1470 | 110HP140 | DHTD 1048 9,525 M 14    | 110 | 4010858036577 |
| RR1471 | 110HP150 | DHTD 1048 9,525 M 18    | 110 | 4010858036584 |
| RR1472 | 094HP250 | HTD 895 9,525M 25       | 94  | 4010858036607 |
| RR1473 | 130DL150 | ZZP                     | 130 | 4010858037079 |
| RR1474 |          | CHDN 1105 9,525M 22     | 116 |               |
| RR1475 |          | CHDN 810 9,525M 22 ZZP  | 85  |               |
| RR1476 |          | STD 1040 8000 M 20      | 130 |               |
| RR1477 |          | STDB 464 S8M 17         | 58  |               |